

45 Progress Road Leigh-on-Sea SS9 5PR

Time and materials



Customer	R51184 - VEOLIA ES (UK) LIMITED	Resource	GID Daniel - Luke
Contact	Greg Bennie		
Address	Burnt Mills Industrial Estate Archers	Job type	Repair
	Field Road Basildon	Reference	R51184 - Veolia ES (UK) Limi-9855
	SS13 1DN	Date	16/03/2023 14:00 - 14:40
Billing address	Veolia ES (UK) Limited Burnt Mills Industrial Estate Archers Field Road Basildon SS13 1DN	Job duration Driving duration	00:40:00 01:00:17

Notes 1242-12420 ECO ELECTRIC SINGLE PHASE

(5400mm x 4375mm) - damage to runners due to high winds - sending photos over

Customer notes


Signed on behalf of client


Resource notes

Distance travelled

10 x LH steel endlocks

10 x RH steel endlocks required





31.1 mi

REPAIR -		
	Answer	Notes
Enter WHAT3WORDS location data	///keen.sunset.swung	
Location description	DOOR 3 Outside right	
Door Height mm top of plate	4375	
Door Width mm over guides	5400	



45 Progress Road Leigh-on-Sea SS9 5PR

Door Type

Roller Shutter

Photo of Service wallet or original manufacturers ID plate with serial number. ESSENTIAL IF NOT OUR DOOR



Serial / Asset number / original manufacturers reference id

1242-12420

Photo of damage





45 Progress Road Leigh-on-Sea SS9 5PR

Inside - door before repair



Outside - Complete door before repair



Inside - Complete door after repair





45 Progress Road Leigh-on-Sea SS9 5PR

Completed Service record



Has door been left working?

11

Work completed general description

Assessed damage to door,

Removal of guides required in order to reallign curtain and replace damaged steel endlocks.

Outside LH guide needs to be redrilled, tapped and countersunk.

Guide to be refitted and door tested and left in working order.

 List of materials used
 None

 Can you connect to GFA app?
 No

 Type of operation
 Deadman

 Door Risk Assment
 Door condemned do not use under any circumstance

Is door under service contract Yes

•

Further works required ? Yes

Survey - Further works shutters		
	Answer	Notes
Revel or face fix ?	Face	
What controls and safeties does this door have ?	Deadman	



45 Progress Road Leigh-on-Sea SS9 5PR

Is there a safety brake ?	Yes
Door Finish	Powder coated
RAL colour	6010
Is the shutter fully accessible ?	Yes
Misc details any other works required by others?	No
How many hours to do the job ?	3

Relevant pic 1/6



Relevant pic 2/6



Survey selection sheet		
	Answer	Notes
What door type are you surveying?	Roller shutter	



45 Progress Road Leigh-on-Sea SS9 5PR