

## INTER-TENANCY MAINTENANCE CHECKLIST

Ref: HDT56679

Site Address	C	lient	Engineer	Inspection Date
Flat 1, 15 Tavistock Street, London WC2E 7PA	c/o CBRE		lain Watson	26 Jan 2024
	Complia	nce/Safety		
Smoke/CO2 alarms fitted, in date and working				
	Cle	aning		
Property professionally cleaned to a satisfactory standard				
	Ge	neral		
Remove items left by tenant				
Painting required including walls, ceilings and woodwork				
Blinds functioning and cleats in place				
Floor coverings clean and undamaged				
Lighting working throughout and lightbulbs replaced if required				
	Se	curity		
Main door operating correctly				
All internal doors in good order and operating correctly				
All locks engaging securely				
Window glazing satisfactory				
Secondary glazing satisfactory				
Ironmongery and locks in place				
	Не	ating		
Boiler is in full working order	Pass	1234		
Radiators are in full working order	Fail	5678		
	Ki	tchen		
Kitchen appliances undamaged				
All white goods and appliances in working order				
Kitchen cupboards and worktops undamaged				
	Bat	hroom		
Tiling and grouting undamaged				
Taps, shower head, hose and riser undamaged				
Shower screen undamaged including seals				
Free flowing drainage				
Bathroom extract in working order				
Sealant in good order				

















